



Model DML812 Parts List

A = Standard Equipment

O = Circuit Diagram

Item#	Part#	Description	Q'ty	Unit
001	GM00001322	SCREW 2.6X8 PB	4	PC.
002	GM00002203	LENS COVER ASSY	1	PC.
003	GM00002204	LENS	1	PC.
004	GM00002205	LENS O-RING	1	PC.
005	GM00002206	REFLECTION CUP COVER	1	PC.
006	GM00002207	LED O-RING	4	PC.
007	GM00002208	O-RING	1	PC.
008	GM00002209	REFLECTION CUP	1	PC.
009	GM00001322	SCREW 2.6X8 PB	4	PC.
010	GM00002211	O-RING	1	PC.
011	GM00002247	LED & HEAT SINK ASSY	1	PC.
012	GM00002218	RIGHT LATCH PLATE	1	PC.
013	GM00002217	LEFT LATCH PLATE	1	PC.
014	GM00002219	SCREW 2.6X7 KB	4	PC.
015	GM00002219	SCREW 2.6X7 KB	4	PC.
016	GM00002220	LIGHT HEAD CASE ASSY	1	PC.
017	GM00002212	SCREW 3X8 PM	2	PC.
018	GM00002221	HOUSING ASSY	1	SET
	D10	INC. 25		
019	GM00002225	LATCH PIN	1	PC.
020	GM00002224	COMPRESSION SPRING	1	PC.
021	GM00002251	SPRING CLIP 2X10X25	1	PC.
022	GM00002237	RIGHT HOUSING COVER	1	PC.
023	GM00002226	SHAFT O-RING	2	PC.
024	GM00002219	SCREW 2.6X7 KB	4	PC.
025	GM00002221	HOUSING ASSY	1	SET
	D10	INC. 18		
026	GM00002222	LINE PRESSING BLOCK	1	PC.
027	GM00002250	SCREW 2.0X5 KB	1	PC.
028	GM00002248	LEFT HOUSING COVER ASSY	1	PC.
029	GM00002251	SPRING CLIP 2X10X25	1	PC.
030	GM00002224	COMPRESSION SPRING	1	PC.
031	GM00002225	LATCH PIN	1	PC.
032	GM00002226	SHAFT O-RING	2	PC.
033	GM00002219	SCREW 2.6X7 KB	4	PC.
034	GM00001012	SCREW 3X12 PB BLACK ZN	5	PC.
035	GM00002231	STRAP HOOK	1	PC.
036	GM00002249	SWITCH SPRING	1	PC.
037	GM00002230	WHITE SWITCH ASSY	1	PC.
038	GM00001292	RING (B3103184009)	1	PC.
039	GM00002252	SILICONE & HEAT SINK	1	PC.
040	GM00002229	MAIN PCBA	1	PC.
041	GM00001322	SCREW 2.6X8 PB	2	PC.
042	GM00002232	SWITCH RUBBER	1	PC.
043	GM00002233	SWITCH SUPPORT	1	PC.
044	GM00002235	PCBA & TERMINAL ASSY	1	PC.
045	GM00002238	HOUSING HOOK	1	PC.
A01	GM00002239	STRAP HOOK ASSY	1	PC.